


# NEW HOLLAND Ford



Tel: +(0)44 1925 850082 Fax: +(0)44 1925 850083  
www.spwaterpumps.co.uk

TYPE OR MODEL	ENGINE	WATER PUMP	REPAIR KIT
<p>TM115, TM120, TM125 TM135, DUAL COMMAND</p> <p>6 CYL—7500 cc</p> <p>M100, M115, TM120 DUAL COMMAND</p> <p>115 mm Diameter Impeller</p>	<p>POWERSTAR 7.5, 7.5T</p> <p>SP1447</p> <p>87801641 82847714 87801636 87840823 87841225 101290039</p>	<p><b>164.128</b></p> 	
<p>TM155, TM175, TM190 POWER COMMAND</p> <p>6 CYL—7500 cc</p> <p>TM115, TM170, TM190</p> <p>126 mm Diameter Impeller</p>	<p>TM155, TM170 M190</p> <p>SP1448</p> <p>87802495 87802496 87384588 87802491 87902493 101290040</p>	<p><b>164.130</b></p> 